





Suthers Star Garage  
 Liverpool Old Rd  
 Preston, PR4 5JS  
<http://suthers-stargarage.co.uk/>  
 Contact No: +44 01772 612281  
 Scanned On :  
 By: Phillip Suthers

VIN	WAUZZZGY6PA106855
Vehicle	0
License Plate	- X8SGC - -



- The sample collected for this tire indicates the Tread Depth is minimal and replacement is recommended soon. See your service advisor.
- Check for minor outside wear on this tire. Consider a wheel alignment. See your service advisor.
- Check for abnormal tire wear. See your service advisor.





- The sample collected for this tire indicates the Tread Depth is safe, replacement not needed today. See your service advisor.



**POSSIBLE SERVICES**


ALIGNMENT INSPECTION NEEDED

**ALIGNMENT ALIGNMENT**



- The sample collected for this tire indicates the Tread Depth is minimal and replacement is recommended soon. See your service advisor.

- The sample collected for this tire indicates the Tread Depth is safe, replacement not needed today. See your service advisor.
- Check for accelerated outside wear on this tire. Consider a wheel alignment. See your service advisor.
- Check for abnormal tire wear. See your service advisor.

 Stopping Distance Degraded

